

C A R W A S H NEWS

April 2019

WASH SELECT II SOFTWARE UPGRADE



In response to the use of EMP (electro-magnetic pulse) devices in the South, Unitec is releasing a software update for use with our Wash Select II® entry systems.

Software version 5.56 is now available for stand-alone Wash Select II units only. This software is not for use with Wash Select II units using a Sierra server, or units processing credit through Gilbarco or Verifone POS register systems. A software release for Sierra-based products (Portal, Sentinel and Wash Select II with Sierra) is forthcoming. If you would like your software upgraded, please contact our parts department.

ROWE PARTS AVAILABILITY

We are starting to receive some parts for Rowe changers, however drive belts are still not available. These are typically replaced during every overhaul. Right now we have no ETA from the manufacturer on an availability date. Because most of the Rowe changers in the field are 10-20 years old, this may be a good time to look at upgrading to a new changer with a Mars validator. These typically have much longer cycles between repairs, saving substantial money in the long run. We are going to offer replacement bill changers from American Changer in this month's Specials for those of you who would like to upgrade.



For more information and pricing on the AC2005 please see the April 2019 Specials.



Place your order at least **30 minutes** before you come. It will be ready when you get here!

303.322.2232
(local)

800.922.1313
(toll free)

Warehouse Hours **7:00 a.m. - 4:00 p.m.** Monday - Friday